

## **PATENT PRODUCT** Grille Installation Instruction

Rev. 150116

Part#		GR12HEJ18C		Applicati	on For 2	For 2005-2006 Lincoln Navigator					
Parts List		ltem	Part Nan	ne QTY	Descriptio	on Item	Part Name	(	QTY	Description	
		1	Billet Grille	2	Stainless stee	el 3	Truss Socket Tapping S	Screws	8	8#×1″	
		2	U Shape Tat	os 2		4	U-Clip Nuts		10	8#	
Install Notes: Overlay $\checkmark$ Replacement $\times$ Drill $\checkmark$ Cut $\checkmark$											
Step	Description						illustration				
1	Identify the grille & hardware with parts list.										
2	Tape off the area around the bumper opening, to protect the vehicle from being scratched during the install.										
3	Using a body saw you will need to cut out the horizontal, and the vertical section of the bumper factory bumper.See figure 1&2.The results are shown in figure 3.Use caution when cutting out the plastic section near the ends of the bumper opening.										
4	Once the bumper section has been cut out, you may use a flat file or sandpaper to file or smooth down the rough cut.										
5	Next the place the U-clip nuts over the two brackets as seen in figure 4.										
6	Now place the upper billet grille into the opening of the bumper, center the billet, then place the brackets, with the leg of the brackets facing you, through the lower section of the bumper and secure to the upper billet using the #8 screw. See figure 5.										
7	Next secure the lower portion of the bumper grille following (6).										
8	Now drill a small pilot hole into the plastic portion of the bumper opening, using the tab on the billet grille as a template.Secure using the #8 screws.										
9	Make sure the billet grille is centered and tighten the fasteners.										
10	Installation completed!!!										
Figure 1 Figure 2 Figure 3											
Figure 4											

strongly recommend the professional installer for best result. Please use masking tape and tape the OEM grille shell along the edge to protect your vehicle during installation. We are not responsible for any damage caused by the installation. Thank you for choosing our product!