

Grille Installation Instruction

Rev. 180701

| Part# | GR08FGA32A/H | | Application | | For 2005-2006 Honda CR-V | | | | |
|--------------------------------------|---|---------------|-------------|-------------|--------------------------|------|-------------------------|-----|-------------|
| | Item | Part Name | QTY | Description | | Item | Part Name | QTY | Description |
| Parts Lis | t 1 | Billet Grille | 1 | Aluminum | | 3 | Fully Threaded Studs | 4 | 10-24X2" |
| | 2 | K-Lock Nuts | 4 | 10#-24 | | 4 | Double Punched Brackets | 2 | |
| Install Notes: Overlay Replacement | | | | | | | | | |
| Step | Description | | | | illustration | | | | |
| | Identify the grille & hardware with parts list. | | | | | | | | |
| | Using a flat blade screwdriver remove the 8 plastic clips the hold the upper portion of the grille shell and the front fascia to the filler panel and the vehicle. Figure 1. | | | | | | | | |
| | Remove the bolt that goes through the battery hold down and the plastic filler panel. Then remove the plastic filler panel and set it aside as it will be reused later. Figure 2. | | | | | | | | |
| | Gently rock the grille shell forward and remove the 2 plastic clips that hold the bottom portion of the grille shell to the front fascia. Figure 3. | | | | | | | | |
| Figure 2 Figure 3 | | | | | | | | | |
| 5 | Remove the factory grille shell. | | | | | | | | |
| 6 | Install the fully threaded studs into the backside of the billet bumper grille. | | | | | | | | |
| 7 | Center the billet grille into the bumper pocket. | | | | | | | | |
| 8 | Place the powder coated brackets over the fully threaded studs and hold in place using the k-lock nuts. | | | | | | | | |
| 9 | Reinstall the black plastic cover which was removed in step 5. | | | | | | | | |
| 10 | Installation completed!!! | | | | | | | | |

The instruction here is for your reference only. You may need to bend the grille a little bit to adjust to fit. We strongly recommend the professional installer for best result. We are not responsible for any damage caused by the installation. Thank you for choosing our product!